## MARYLAND HISTORICAL TRUST DETERMINATION OF ELIGIBILITY FORM

NR Eligible:	yes	
	no	

Property Name: Cupler Property	Inventory Number: G-I-A-225							
Address: 211 Windy Acres Lane	Historic district: yes X no							
City: Grantsville vicinity Zip Code: 21536	County: Garrett							
USGS Quadrangle(s): Avilton								
Property Owner: John A. Cupler Family Trust	ax Account ID Number: 1203010880							
Tax Map Parcel Number(s): Tax Map Number	r:09							
Project: U.S. 219 Improvements, Meyersdale (Pa.) to I-68 Agency	FHWA, SHA							
Agency Prepared By: Heberling Associates for SHA								
Preparer's Name: William Hunter	Date Prepared:6/15/2005							
Documentation is presented in: W.M. Hunter 2003 [2005] Historic Structures Survey/Determination of Eligibility Report, U.S. 219 Improvements Project. Prepared for the FHWA and SHA by Heberling Associates, Inc.								
Preparer's Eligibility Recommendation: Eligibility recommended	X Eligibility not recommended							
Criteria:ABCD Considerations:AB	CDEFG							
Complete if the property is a contributing or non-contributing resource	to a NR district/property:							
Name of the District/Property:								
Inventory Number: Eligible:yes	Listed: yes							
Site visit by MHT Staf yesX no Name:	Date:							
Description of Property and Justification: (Please attach map and photo)								
The Cupler Property is an example of the reuse of elements of a relic farmstead, a now 94.32-acre tract located above the Casselman River on the western slope of Chestnut Ridge. The original houses are gone, as are many of the outbuildings, but the barn remains as the core of a c. 1974 residence and small commercial establishment, a wellness store. Some of the original materials from the house were reincorporated into the new house and surroundings. In addition to the redeveloped barn, the property features a modern garage, swimming pool, a rebuilt springhead, a rebuilt springhouse, the vague ruins of a sugar camp and a pool house. The trace of the old Salisbury Road bisects the property from north to south.								
	th to south.  n of the barn, known for its size and full size we to an earlier log house on the slope to the forebay was enclosed, a shed was built off of Local informants suggest that the barn once such details are impossible to discern from its							
and a pool house. The trace of the old Salisbury Road bisects the property from nor The property once featured a c. 1860 two-story five-bay Georgian-form house south rear wing. The house was razed in the early 1970s. The barn, first constructed relationst, was a large five-bay standard Pennsylvania barn modernized c. 1940, when its the front, and a concrete block milk house was constructed off its southeast corner. had an overshoot on its eastern gable end, though the original form of the barn and	th to south.  n of the barn, known for its size and full size we to an earlier log house on the slope to the forebay was enclosed, a shed was built off of Local informants suggest that the barn once such details are impossible to discern from its							
and a pool house. The trace of the old Salisbury Road bisects the property from nor The property once featured a c. 1860 two-story five-bay Georgian-form house south rear wing. The house was razed in the early 1970s. The barn, first constructed relative east, was a large five-bay standard Pennsylvania barn modernized c. 1940, when its the front, and a concrete block milk house was constructed off its southeast corner. had an overshoot on its eastern gable end, though the original form of the barn and current reconstructed form. The barn was converted into the principal residence in	th to south.  n of the barn, known for its size and full size we to an earlier log house on the slope to the forebay was enclosed, a shed was built off of Local informants suggest that the barn once such details are impossible to discern from its							
and a pool house. The trace of the old Salisbury Road bisects the property from nor The property once featured a c. 1860 two-story five-bay Georgian-form house south rear wing. The house was razed in the early 1970s. The barn, first constructed relative east, was a large five-bay standard Pennsylvania barn modernized c. 1940, when its the front, and a concrete block milk house was constructed off its southeast corner. had an overshoot on its eastern gable end, though the original form of the barn and current reconstructed form. The barn was converted into the principal residence in  MARYLAND HISTORICAL TRUST REVIEW  Eligibility recommended Eligibility not recommended	th to south.  n of the barn, known for its size and full size we to an earlier log house on the slope to the forebay was enclosed, a shed was built off of Local informants suggest that the barn once such details are impossible to discern from its							
and a pool house. The trace of the old Salisbury Road bisects the property from nor The property once featured a c. 1860 two-story five-bay Georgian-form house south rear wing. The house was razed in the early 1970s. The barn, first constructed relative east, was a large five-bay standard Pennsylvania barn modernized c. 1940, when its the front, and a concrete block milk house was constructed off its southeast corner. had an overshoot on its eastern gable end, though the original form of the barn and current reconstructed form. The barn was converted into the principal residence in MARYLAND HISTORICAL TRUST REVIEW  Eligibility recommended Eligibility not recommended	th to south.  n of the barn, known for its size and full size we to an earlier log house on the slope to the forebay was enclosed, a shed was built off of Local informants suggest that the barn once such details are impossible to discern from its 1974.							
and a pool house. The trace of the old Salisbury Road bisects the property from nor The property once featured a c. 1860 two-story five-bay Georgian-form house south rear wing. The house was razed in the early 1970s. The barn, first constructed relative east, was a large five-bay standard Pennsylvania barn modernized c. 1940, when its the front, and a concrete block milk house was constructed off its southeast corner. had an overshoot on its eastern gable end, though the original form of the barn and current reconstructed form. The barn was converted into the principal residence in MARYLAND HISTORICAL TRUST REVIEW  Eligibility recommended Eligibility not recommended C D Considerations: A	th to south.  n of the barn, known for its size and full size we to an earlier log house on the slope to the forebay was enclosed, a shed was built off of Local informants suggest that the barn once such details are impossible to discern from its 1974.  B _ C _ D _ E _ F _ G							
and a pool house. The trace of the old Salisbury Road bisects the property from nor The property once featured a c. 1860 two-story five-bay Georgian-form house south rear wing. The house was razed in the early 1970s. The barn, first constructed relative east, was a large five-bay standard Pennsylvania barn modernized c. 1940, when its the front, and a concrete block milk house was constructed off its southeast corner. had an overshoot on its eastern gable end, though the original form of the barn and current reconstructed form. The barn was converted into the principal residence in MARYLAND HISTORICAL TRUST REVIEW  Eligibility recommended Eligibility not recommended C D Considerations: A	th to south.  n of the barn, known for its size and full size we to an earlier log house on the slope to the forebay was enclosed, a shed was built off of Local informants suggest that the barn once such details are impossible to discern from its 1974.							
and a pool house. The trace of the old Salisbury Road bisects the property from nor The property once featured a c. 1860 two-story five-bay Georgian-form house south rear wing. The house was razed in the early 1970s. The barn, first constructed relative east, was a large five-bay standard Pennsylvania barn modernized c. 1940, when its the front, and a concrete block milk house was constructed off its southeast corner. had an overshoot on its eastern gable end, though the original form of the barn and current reconstructed form. The barn was converted into the principal residence in SMARYLAND HISTORICAL TRUST REVIEW  Eligibility recommended Eligibility not recommended Criteria: A B C D Considerations: A  MHT Comments:	th to south.  In of the barn, known for its size and full size we to an earlier log house on the slope to the forebay was enclosed, a shed was built off of Local informants suggest that the barn once such details are impossible to discern from its 1974.  B _ C _ D _ E _ F _ G							

## NR-ELIGIBILITY REVIEW FORM

G-I-A-225

Cupler Property

Page 2

The Cupler Property may be located on the site of the Hans Casper Durst home place, first developed as early as 1769 by the Swiss immigrant and progenitor of the Durst family in the region. The only material element that may be associated with Casper Durst is the "little house," a stylized springhouse found near the c. 1860 house site, south of the core buildings. This structure features a partially excavated rough-sandstone foundation and half-timber frame that may indeed date from the late 18th century. Adjacent foundation remnants, a concrete block chimney and a modern foyer addition demonstrate the changes to the building over time; the building may have once served as a schoolhouse. The current owners stripped and rehabilitated the building in the early 1970s, incorporating its structural elements into a stylized Tudor cottage design featuring heavily glazed multi-paned windows and stucco wall treatment.

The loss of at least two early residences, destruction of most outbuildings, the reconstruction of the barn as a residence, and the development of the original property, combine with the alterations to and reconstruction of the springhouse to strain the historic associations necessary for National Register consideration. The Cupler Property is at the head of a residential development on the west slope of Meadow Mountain and is now a thoroughly modern complex. Suffering from a dramatic loss of integrity, the Cupler Property is not eligible for the National Register of Historic Places under Criteria A, B or C. In spite of some disturbance, there are likely archaeological remains associated with the now-razed farm buildings.

MARYLA	ND HISTO	RICAL	TRUST	REVI	EW							
Eligibility recommended				Eligibility not recommend			_					
Criteria: MHT Com	A ments:	В -	C _	D	Considerations:	A	B	c	D	E	F	_ <sup>G</sup>
Reviewer, Office of Preservation Services						Date					_	
-	Reviewer, National Register Program					Date						

Cupler Property


c. 1974

211 Windy Acres Lane

Grantsville

Private

The Cupler Property is an outstanding example of the adaptive reuse of a relic farmstead, the now 94.32-acre tract located above the Casselman River on the west slope of Chestnut Ridge. The original house is gone, as are many of the outbuildings, but the barn remains as the core of a c. 1974 residence and small commercial establishment, a wellness store. Some of the original materials from the house were reincorporated into the new house and surroundings. In addition to the redeveloped barn, the property features a modern garage, a rebuilt springhead, swimming pool and pool house, and a rebuilt springhouse known as the "little house," a stylized springhouse found near the c. 1860 house site, south of the core buildings. This structure features partially excavated rough-sandstone foundation and a half-timber frame that may indeed date from the late 18<sup>th</sup> century. The current owners stripped and rehabilitated the building after 1974, incorporating its structural elements into a stylized Tudor cottage design featuring heavily glazed multi-paned windows and stucco cladding. The Cupler Property is at the head of a residential development on the west slope of Meadow Mountain. Suffering from an overwhelming loss of integrity, the Cupler Property is not eligible for the National Register of Historic Places.





GARRETT COUNTY, MARYLAND
HEBERLING ASSOCIATED TWO. (AUGUST 2003)
UIEW OF BARN AND HOUSE, FACING EAST.
PHOTO
1 DE E



GARRETT COUNTY, MARYLANDS
HEBERUNG ASTOCIOTES, THE. (ANGUST 2003)
VIEW OF BARN, FACING SOUTH.
PHOTO 2 OF E



G.I.M. ZZS (COPELA PROPERTY) GARRETT COUNTY, MARTENNI HEBERLINE ASSECTATES, THE (MOSER-SER - 904) VIEW OF THE "LITTLE HOUSE" FACING SOUTH PHOTO 3 OF 5



GIA-228 CLUPLER PROPERTY)

GARRETT COUNTY, MARYLAND

HEREALING MORGENTEI, THE (MONEMERS 2004)

VIEW OF THE "LITTLE MONSE" FACING MORGHEAST

PHOTO 4 OF 5



G-I.A. 225 (CUPLER PROPERTY) GARRETT COUNTY, MARYLAND HEBERLINE ASSOCIATES THE CHOURMER 2004) VIEW OF THE MODERN SPRINGHOUSE, FACING SCUTHER Puero Son 5.